ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M02954
Date Received: 09/04/08
Date Extracted: 09/08/08
Date Analyzed: 09/08/08
Matrix: Water
Units: ug/L (ppb)

Internal Standard:

Germanium

Client: Project: Lab ID: Data File: Alaskan Copper Works PO M02954, F&BI 809032

809032-01 x10 809032-01 x10.027

Instrument: ICPMS1

Operator: hr

% Recovery:

Lower Limit: 60 Upper Limit: 125

Concentration ug/L (ppb)

Chromium 164
Nickel 92.3
Copper 119
Zinc <10

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Client: Alaskan Copper Works
Date Received: Not Applicable Project: PO M02954, F&BI 809032
Date Extracted: 09/08/08 Lab ID: I8-343 mb

Date Analyzed: 09/08/08 Data File: I8-343 mb.014 Matrix: Water Instrument: ICPMS1

Units: ug/L (ppb) Operator: hr

Internal Standard: % Recovery: Limit: Limit: Germanium 89 60 125

Concentration
Analyte: ug/L (ppb)

 Chromium
 <1</td>

 Nickel
 <1</td>

 Copper
 <1</td>

 Zinc
 <1</td>

ENVIRONMENTAL CHEMISTS

Date of Report: 09/10/08 Date Received: 09/04/08

Project: Metro Self Monitor, PO M02954, F&BI 809032

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 809036-21 (Duplicate)

Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria
Chromium	ug/L (ppb)	<1	<1	nm	0-20
Nickel	ug/L (ppb)	1.53	1.44	6	0-20
Copper	ug/L (ppb)	1.07	<1	nm	0-20
Zinc	ug/L (ppb)	1.91	1.62	16	0-20

Laboratory Code: 809036-21 (Matrix Spike)

		Spike	Sample	Percent Recovery	Acceptance
Analyte	Reporting Units	Level	Result	MS	Criteria
Chromium	ug/L (ppb)	20	<1	109	50-150
Nickel	ug/L (ppb)	20	1.53	110	50-150
Copper	ug/L (ppb)	20	1.07	107	50-150
Zinc	ug/L (ppb)	50	1.91	110	50-150

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Unit	Spike s Level	Percent Recovery LCS	Acceptance Criteria
Chromium	ug/L (ppb)	20	102	70-130
Nickel	ug/L (ppb)	20	103	70-130
Copper	ug/L (ppb)	20	100	70-130
Zinc	ug/L (ppb)	50	97	70-130

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com



September 10, 2008

INVOICE #08ACU0910-1

Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M02954, F&BI 809032 - Results of testing requested by Gerry Thompson for material submitted on September 4, 2008.

1 sample analyzed for Total Chromium, Copper, Nickel and Zinc	
by Method 200.8 @ \$85 per sample	\$ 85.00
Rush Charges (4 day) 60% of \$85.00	51.00
Amount Due	\$ 136.00

FEDERAL TAX ID #(b) (6)

809032		recipion de la companya de la compa	SAI	MPLE CHA	//		то	DY		M	E		99	10		108	amartine damentalismentalisment and act of the American action of the citizense of the citi	AD
Send Report To Georges Company AUSKAN Address 628 S.	Copper Hone	mpsou work	k5	PROJECT N Medica			on	701		n	> P	0# 2 75 9	 Y.		Sta YRU	ndard SH	i of IAROUND TIME I (2 Wooks) CCY es authorized by	4
City, State, ZIP Sexuel Phone # 206-571-603	e carpo	981 <u>2</u> 4-382-4	309	REMARKS	3 A 7	a				2.150 (50)	24	9 7			Ret	pose a urn sa	PLE DISPOSAL after 30 days amples with instructions	34
	1776			**************************************					_	C 18 8	77-6	es r	EQU	ES1	'ED)			4
Sample ID	Lab FD	Date	Time	Sample Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 82,60	SVOCs by 8270		Oxens 2		•		4	Notes	-
10295Y	0]	9/4/08	12:00	MD	1							X						
***************************************			r.															
			22 F7														N. k	
		14												7000	12		11 to 2	A
e.	140		N						. 11									N. Carlot
		70		×									I					"
,		3 i																
		and the second		XX-2.89					1	T				800				

Friedman & Bruya, Inc. 3012 16th Avenue West

Seattle, WA 98119-2029

Ph. (206) 285-8282

	•	•		
Fox	(20	6) 28	33- <i>5044</i>	
FORM	8 \0	00\0	OC.DOC	

SIGNATURE	PRINT NAME	COMPANY	DATE	TIME
Relimbershed by	Genero Thompson	ACU	19/1/68	1241PM
Received by: an aun	Whan Phan	TeBI	9/4/08	V
Relinquished by:	22	•		
Received by:			•	

Samples received at 22°C

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

September 10, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on September 4, 2008 from the Metro Self Monitor, PO M02954, F&BI 809032 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU0910R.DOC